

# AC-1004 Wireless LAN Controller FSOS 11.9(6)B5P3S2T1 Software Release Notes

---

Models: AC-1004

## Content

|                                             |          |
|---------------------------------------------|----------|
| <b>1 Version Information .....</b>          | <b>1</b> |
| 1.1 Historical Version Release Record ..... | 1        |
| <b>2 Function Description .....</b>         | <b>1</b> |
| 2.1 Added Features .....                    | 1        |
| 2.2 Changed Features .....                  | 1        |
| <b>3 Fixed Problems .....</b>               | <b>1</b> |
| <b>4 Known Issues .....</b>                 | <b>2</b> |
| <b>5 Compatibility Notes .....</b>          | <b>2</b> |
| 5.1 Hardware Instructions .....             | 2        |
| <b>6 Upgrade Instructions .....</b>         | <b>2</b> |
| 6.1 Upgrade File .....                      | 2        |
| 6.2 Upgrade Requirements .....              | 3        |
| 6.3 Precautions .....                       | 3        |

## 1 Version Information

|                    |                        |
|--------------------|------------------------|
| Version Number     | AC_FSOS11.9(6)B5P3S2T1 |
| Version Type       | Customized version     |
| Applicable         | AC-1004 V1.xx          |
| Products           | AC-1004 V2.xx          |
| Release Type       | Officially release     |
| Release Date       | 2024-12-26             |
| Baseline versions  | AC_FSOS11.9(6)B5P3S2   |
| Reason for release | Bug Revisions          |

### 1.1 Historical Version Release Record

| Release Date | Version Number         | Status          |
|--------------|------------------------|-----------------|
| 2024-07-23   | AC_FSOS11.9(6)B5P3S2T1 | Need to upgrade |

## 2 Function Description

### 2.1 Added Features

None

### 2.2 Changed Features

None

## 3 Fixed Problems

| Question Number | Problem Description                                                                                                 | First Found Version                      |
|-----------------|---------------------------------------------------------------------------------------------------------------------|------------------------------------------|
| BUG-1273265     | After restoring the device to factory settings, the default redirect IP is incorrect, redirecting to 192.168.100.1. | AC_FSOS11.9(6)B5P3S2T1,Release(11191515) |
| BUG-1273242     | The file name for importing black and white lists has character limitations.                                        | AC_FSOS11.9(6)B5P3S2T1,Release(11191515) |

|             |                                                    |                                          |
|-------------|----------------------------------------------------|------------------------------------------|
| BUG-1273270 | The page pop-up messages are displayed in Chinese. | AC_FSOS11.9(6)B5P3S2T1,Release(11191515) |
| BUG-1273270 | Terminal authentication failed.                    | AC_FSOS11.9(6)B5P3S2T1,Release(11191515) |

## 4 Known Issues

None

## 5 Compatibility Notes

### 5.1 Hardware Instructions

| Hardware Model | Hardware Version Number | Description                                                                                                                   |
|----------------|-------------------------|-------------------------------------------------------------------------------------------------------------------------------|
| AC-1004        | V1.xx                   | 1 10/100/1000Base-T adaptive uplink WAN port, 1 4G extended uplink WAN port, 4 10/100/1000Base-T adaptive downlink LAN ports. |
| AC-1004        | V2.xx                   | 1 10/100/1000Base-T adaptive uplink WAN port, 1 4G extended uplink WAN port, 4 10/100/1000Base-T adaptive downlink LAN ports. |

## 6 Upgrade Instructions

### 6.1 Upgrade File

#### 6.1.1 AC-1004 V1.xx

|                     |                                                     |
|---------------------|-----------------------------------------------------|
| File Name           | AC_FSOS11.9(6)B5P3S2T1_G6C4-01_11241711_install.bin |
| File Description    | System upgrade installers, customized versions      |
| File Size           | 44816030 Bytes                                      |
| Applicable Products | AC-1004 V1.xx                                       |
| MD5                 | c716efba9477819b520647799ca047fe                    |
| Software Version    | AC_FSOS11.9(6)B5P3S2T1, Release(11241711)           |

### 6.1.2 AC-1004 V2.xx


|                     |                                                     |
|---------------------|-----------------------------------------------------|
| File Name           | AC_FSOS11.9(6)B5P3S2T1_G6C4-05_11241711_install.bin |
| File Description    | System upgrade installers, customized versions      |
| File Size           | 44935743 byte                                       |
| Applicable Products | AC-1004 V2.xx                                       |
| MD5                 | 89607fd3bbd49ccf8a10d26e669314d0                    |
| Software Version    | AC_FSOS11.9(6)B5P3S2T1, Release(11241711)           |

## 6.2 Upgrade Requirements

None

## 6.3 Precautions

- The upgrade must undergo successful verification in a controlled environment prior to its deployment in the actual field.
- The customer's database should be backed up before conducting an on-site upgrade.
- During the upgrade, refrain from turning off or resetting the system, or plugging or unplugging modules once the message prohibiting rebooting appears.
- During the upgrade/downgrade process, carefully monitor the prompt messages displayed. If a failure occurs, save the log message and contact FS Network technical support.
- After completing the upgrade/downgrade, use the "show version detail" command to confirm the current device version. If the current version matches the target version, the upgrade was successful.



<https://www.fs.com>



The information in this document is subject to change without notice. FS has made all efforts to ensure the accuracy of the information, but all information in this document does not constitute any kind of warranty.